

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 5501445

engine # 5501248

Revised 12/15/04



Date	Mileage	Repair	Category	Notes
10/31/63	100,518	tune up, points and plugs	ignition	
05/07/64	108,584	tune up, points and plugs	ignition	
05/16/64	109,041	front end alignment	chassis	
06/06/64	109,960	carb linkage	fuel	
06/06/64	109,960	oil change and lube	lubrication	
06/20/64	110,000	two tires, wheel balance	tires	
07/18/64	111,749	lube and oil change	lubrication	
08/11/64	112,572	fuel pump repair	fuel	
11/06/64	113,708	valve grinding, head gasket, manifold gasket	motor	
11/15/64	113,708	motor mount	motor	
01/14/65	114,789	lube	lubrication	
01/15/65	114,789	thermostat	cooling	
05/10/65	116,190	tune up, points and plugs	ignition	
05/12/65	116,326	timing, set carb	ignition	
05/15/65	116,380	rebuild carb, tune up	fuel	
09/27/65	117,462	lube and oil change	lubrication	
01/28/66	118,583	valve grinding, head gasket, manifold gasket	motor	
05/01/66	119,000	battery	electrical	
05/30/66	119,619	lube and oil change	lubrication	
05/02/67	122,134	lube and oil change	lubrication	
05/17/67	122,287	rear motor mount	motor	
10/16/67	123,700	new top	body	
03/26/68	125,092	lube and oil change	lubrication	
04/27/68	125,550	repack front bearings, rotate tires	lubrication	
08/03/68	127,391	lube and oil, plugs, adjust valves	lubrication	
08/05/68	127,474	4 tires and wheel balancing	tires	
08/18/68	127,685	balance front wheels	tires	
09/02/68	127,791	wiper blades	body	
10/05/68	99,516	two tires, wheel balance	tires	
10/31/68	131,300	replace left motor mount	motor	
11/25/68	131,388	boil radiator, flush engine, water hoses	cooling	
01/15/69	132,137	battery	electrical	
05/24/69	133,000	HDDUP	motor	
10/05/69	135,000	clean plugs, adjust carb	fuel	
10/09/69	136,000	fuel hose parts	fuel	
12/15/69	136,632	repair front end	chassis	
02/24/70	137,152	grind valves	motor	
02/24/70	137,152	clean carbs, plugs	fuel	
03/15/70	137,273	4 tires, wheel balance	tires	
06/11/70	139,907	oil change and filter	lubrication	
06/11/70	139,907	transmission fluid change	drive train	
09/12/70	140,500	muffler and hangers	exhaust	
10/19/70	142,500	repaint	body	
10/19/70	142,500	hub caps	body	
10/29/70	142,835	rebuild generator	electrical	
02/23/71	144,935	rebuild clutch and t/o bearing	drive train	
03/18/71	145,300	front brake lines	brakes	
04/05/71	145,634	thermostat	cooling	drilled holes in thermostat to allow passage of water when closed
05/14/71	146,339	balance and rotate tires	tires	
05/25/71	146,454	oil and lube	lubrication	
06/15/71	147,014	adjust timing and valve tappet clearance	motor	

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 5501445

engine # 5501248

Revised 12/15/04



Date	Mileage	Repair	Category	Notes
10/20/71	150,000	wiper blades	body	
08/07/72	154,530	oil and lube	lubrication	
08/09/72	154,595	points and plugs	ignition	
02/26/73	155,000	water hoses, belt, and temp gauge	cooling	
03/18/73	157,012	4 tires and wheel balance	tires	
06/05/73	159,367	refurb vinyl interior (new dash and door top rails)	interior	
06/06/73	159,377	muffler	exhaust	
06/08/73	159,442	adjust valves and timing	motor	
08/09/73	160,512	repair seat frames	interior	
08/10/73	160,512	shift boot	interior	
11/10/73	162,353	plugs	ignition	
11/28/73	162,620	points plugs and valves	motor	
12/17/73	163,201	adjust valves and rework cylinder head, new valves	motor	
12/21/73	163,201	repair cylinder head, weld	motor	
12/28/73	163,088	basket and belt	cooling	
01/22/74	163,609	oil change and lube	lubrication	
04/24/74	165,543	throttle return spring	fuel	
04/01/75	169,700	starter motor	electrical	
05/16/75	169,700	switch and boot	electrical	
07/16/75	171,145	replace starter motor	electrical	
10/10/75	172,497	points, plugs rotor	ignition	
01/06/76	174,088	scope engine	motor	
10/06/76	174,104	rebuild engine (top)	motor	
11/05/76	174,250	voltage regulator	electrical	
03/09/77	174,679	battery	electrical	
04/06/77	174,712	rebuild carbs, cam and timing chain	motor	
09/04/77	176,800	4 tires and wheel balance	tires	
10/18/77	177,000	rebuild generator	electrical	
01/17/78	178,000	new top	body	
05/12/78	179,540	oil and lube	lubrication	
05/19/80	180,000	paint car	body	
10/03/80	180,492	battery	electrical	
01/21/81	181,000	tire tube	tires	
05/06/82	181,000	voltage regulator	electrical	
06/10/82	180,000	charging light	electrical	
03/25/83	181,000	starter	electrical	
06/14/86	181,000	brake shoes	brakes	
09/01/93	181,141	brake cylinders, master brake cylinders rebuild	brakes	
03/15/95	181,141	battery	electrical	
06/15/99	181,579	tail light lenses	body	
06/15/99	181,579	front turn signal reflector assembly	body	
06/15/99	181,579	all new bulbs and fuses	electrical	
07/19/99	181,579	hoses	cooling	
07/19/99	181,579	new outside mirror	body	
07/23/99	181,579	blower motor	ventilation	
08/04/99	181,579	steering wheel and horn button	interior	
08/28/99	181,579	stereo addition	interior	
08/28/99	181,579	new pedal pads	interior	
08/28/99	181,579	front end rebuild	chassis	all new bushings, tie rod ends, king pins, seals, rebuild zerz fittings, repainted control arms, and new shocks
08/28/99	181,579	brake rebuild front end	brakes	new pads, cylinders kits, hoses

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 5501445

engine # 5501248

Revised 12/15/04



Date	Mileage	Repair	Category	Notes
08/28/99	181,579	4 tires, plus new spare	tires	
08/28/99	181,579	rebuilt heater lines	ventilation	
08/28/99	181,579	all new fuel lines, from filter to carbs	fuel	
09/23/99	181,579	all new body gaskets, eyebrow trim, and window trim	body	
10/18/99	181,579	paint and full body work	body	
01/11/00	181,579	vent hoses	ventilation	
01/19/00	181,579	top to windshield seal	body	difficulty closing top now
02/08/00	181,579	new vinyl on rear boot, door tops, and dash	interior	
02/25/00	181,600	carpet set and padding	interior	
02/25/00	181,600	carpet mounting rails	interior	
02/28/00	181,600	all new exhaust, manifold to tail pipe, with hangers	exhaust	
03/01/00	181,650	replace shift bushings and shift boot	drive train	
03/01/00	181,650	replace seat belts per factory specifications	interior	
03/15/00	181,741	oil change and lube	lubrication	
03/15/00	181,741	points, plugs, rotor, spark plug wires, dist cap	ignition	
03/15/00	181,741	shift lever bushings	drive train	
03/24/00	181,762	rewire alternator to regulator	electrical	
03/24/00	181,762	replace all cooling hoses	cooling	radiator to motor, and radiator to manifolds
03/24/00	181,762	removal and cleaning of intake manifolds	fuel	cooling lines were blocked
03/24/00	181,762	jb weld new studs into carb bodies for air log	fuel	
03/24/00	181,762	jb weld screws for accelerator pump on carb #1	fuel	
03/24/00	181,762	rebuild the carbs, new secondary diaphragms, new pump diaphragms, new mounting gaskets and bushings.	fuel	note that the new needle valves did not work
03/24/00	181,762	replaced hot choke cable and switch	fuel	
03/24/00	181,762	rebuild window guides using felt channel instead of original blocks	body	
04/05/00	181,807	installed rebuilt steering box	chassis	greatly improved steering!
04/06/00	181,807	replace transmission fluid	drive train	when the plug was pulled, there was no fluid!
05/15/00	182,000	change coolant	cooling	
05/15/00	182,000	manifold gasket replacement	motor	this stopped the high idle, apparently an air leak existed
10/20/00	182,720	replace timing chain tensioner	motor	the old one was missing an internal part that kept the pressure significant
10/20/00	182,800	Oil change and filter	lubrication	
10/20/00	182,800	glued stud in carb, and stud on air log support	motor	used West Systems with high density filler instead of JB weld
10/20/00	182,800	Replaced left side engine cover	motor	cleaned out the "gunk" inside the motor, there was significant buildup
10/20/00	182,800	changed coolant	cooling	
10/20/00	182,800	Replaced bushing on the intermediate steering linkage arm	chassis	
10/20/00	182,800	Installed carb fuel overflow drain	fuel	this was missing
10/20/00	182,950	Replaced oil pressure hose from filter to firewall	lubrication	
02/15/01	182,960	Replaced bushing in #1 carb for choke.	fuel	machine shop replaced the bushing, this removed the play in the choke shaft
04/11/01	182,965	Rebuilt idler arm linkage, bushing and new nut	chassis	machine shop replaced the bushing
06/15/01	182,977	Recovering the interior dash, back and door tops in leather	interior	GAHH 1079, dark red leather, new trim
06/15/01	182,977	Repainted rear of car, and instrument panel	body	

