

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 551445

10/03/10



**Date            Mileage            Cost            Repair**

10/02/10	186,382	140.00	Radiator removal and cleaning
10/02/10	186,382	330.00	Waterpump replacement, gaskets, seals
10/02/10	186,382	106.00	Motor mounts and limiters
10/02/10	186,382	15.00	Generator bracket adhytment stud, new electrical wires
07/15/09	186,000	-	tune up, points and plugs
07/01/07	185,776	15.00	Replaced Coolant
07/01/07	185,776	15.00	changed oil
07/01/07	185,776	204.65	replaced manifold gasket, manifold nuts
05/05/07	185,635	-	Repair rattles in dash by bushing climate control levers
05/05/07	185,635	156.00	Replaced left side window pillar top clamp
09/01/05	185,000	30.00	Repair right heater core
11/17/04	185,000	66.00	Fuel pump rebuild kit
11/08/04	184,758	122.00	replace rear brake cylinders
11/08/04	184,758	75.00	carb float valves
10/25/04	184,758	2,000.00	repair steering
10/25/04	184,758	447.00	replace front brake cylinders
08/20/04	184,500	85.00	misc parts - dipstick, gas cap seal, wiper refills
02/07/04	184,000	75.59	Replace battery
02/07/04	184,000	176.75	rebuild generator
01/06/03	183,615	108.34	Replaced front bearings
12/15/02	183,000	420.00	Recover seats, and rebuild seat frames - new fasteners
12/15/02	183,000	39.95	Replaced Hirschman antenna
11/27/02	183,615	192.38	Rebuilt differential - new seals, paint, connecting pin
11/27/02	183,615	67.50	Replaced e-brake cable
11/27/02	183,615	156.75	Replaced rear bearings
11/27/02	183,615	171.95	Replaced all rear rubber mounts
10/07/02	183,615	249.45	Clutch TO bearing and pressure plate replacement
10/07/02	183,615	117.35	Rebuild transmission, replace all seals and mount
10/07/02	183,615	117.50	Replaces indicator escutcheons on dash
07/15/02	183,500	50.00	Replaced king pin bushings
07/15/02	183,500	10.00	Repainted interior front wheel wells
06/26/02	183,500	74.00	Rechrome rear emblems, and trunk lift
04/15/02	183,500	25.00	Installed new Jensen 4 CD changer in glove box
02/15/02	183,500	200.00	Replaced bushings on throttle shafts
02/15/02	183,500	15.00	Battery terminal covers
01/15/02	183,500	-	Adjusted alternator bracket

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 551445

10/03/10



**Date            Mileage            Cost            Repair**

Date	Mileage	Cost	Repair
08/05/01	183,000	-	Removed and adjusted steering box.
08/05/01	183,000	-	Installed top window seal
08/05/01	183,000	-	Reset timing and idle mixture
07/09/01	182,977	384.02	Repair tack, speedo, fuel gauge and clock
06/15/01	182,977	632.51	Recovering the interior dash, back and door tops in leather
06/15/01	182,977	649.21	Repainted rear of car, and instrument panel
04/11/01	182,965	116.76	Rebuilt idler arm linkage, bushing and new nut
02/15/01	182,960	15.00	Replaced bushing in #1 carb for choke.
10/20/00	182,720	105.61	replace timing chain tensioner
10/20/00	182,800	25.00	Oil change and filter
10/20/00	182,800	-	glued stud in carb, and stud on air log support
10/20/00	182,800	120.00	Replaced left side engine cover
10/20/00	182,800	15.00	changed coolant
10/20/00	182,800	30.00	Replaced bushing on the intermediate steering linkage arm
10/20/00	182,800	220.00	Installed carb fuel overflow drain
10/20/00	182,950	21.50	Replaced oil pressure hose from filter to firewall
05/15/00	182,000	15.00	change coolant
05/15/00	182,000	50.00	manifold gasket replacement
04/06/00	181,807	15.00	replace transmission fluid
04/05/00	181,807	250.00	installed rebuilt steering box
03/24/00	181,762	1.00	rewire alternator to regulator
03/24/00	181,762	8.50	replace all cooling hoses
03/24/00	181,762	-	removal and cleaning of intake manifolds
03/24/00	181,762	3.50	jb weld new studs into carb bodies for air log
03/24/00	181,762	-	jb weld screws for accelerator pump on carb #1
03/24/00	181,762	120.00	rebuild the carbs, new secondary diaphragms, new pump diaphragms, new mounting gaskets and bushings.
03/24/00	181,762	60.00	replaced hot choke cable and switch
03/24/00	181,762	40.00	rebuild window guides using felt channel instead of original blocks
03/15/00	181,741	15.00	oil change and lube

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 551445

10/03/10



**Date            Mileage            Cost            Repair**

03/15/00	181,741	59.00	points, plugs, rotor, spark plug wires, dist cap
03/15/00	181,741	5.10	shift lever bushings
03/01/00	181,650	20.10	replace shift bushings and shift boot
03/01/00	181,650	25.00	replace seat belts per factory specifications
02/28/00	181,600	745.00	all new exhaust, manifold to tail pipe, with hangers
02/25/00	181,600	685.00	carpet set and padding
02/25/00	181,600	77.20	carpet mounting rails
02/08/00	181,579	328.00	new vinyl on rear boot, door tops, and dash
01/19/00	181,579	76.22	top to windshield seal
01/11/00	181,579	36.00	vent hoses
10/18/99	181,579	6,203.00	paint and full body work
09/23/99	181,579	1,022.00	all new body gaskets, eyebrow trim, and window trim
08/28/99	181,579	225.00	stereo addition
08/28/99	181,579	23.00	new pedal pads
08/28/99	181,579	769.15	front end rebuild
08/28/99	181,579	300.00	brake rebuild front end
08/28/99	181,579	307.00	4 tires, plus new spare
08/28/99	181,579	100.00	rebuilt heater lines
08/28/99	181,579	250.00	all new fuel lines, from filter to carbs
08/04/99	181,579	249.00	steering wheel and horn button
07/23/99	181,579	65.00	blower motor
07/19/99	181,579	14.79	hoses
07/19/99	181,579	47.50	new outside mirror
06/15/99	181,579	271.00	tail light lenses
06/15/99	181,579	75.00	front turn signal reflector assembly
06/15/99	181,579	50.00	all new bulbs and fuses
03/15/95	181,141	65.00	battery
09/01/93	181,141	508.00	brake cylinders, master brake cylinders rebuild
06/14/86	181,000	38.91	brake shoes
03/25/83	181,000	165.00	starter
06/10/82	180,000	5.00	charging light
05/06/82	181,000	56.41	voltage regulator
01/21/81	181,000	9.00	tire tube
10/03/80	180,492	50.87	battery
05/19/80	180,000	530.00	paint car
05/12/78	179,540	17.65	oil and lube
01/17/78	178,000	220.00	new top
10/18/77	177,000	54.28	rebuild generator
09/04/77	176,800	155.61	4 tires and wheel balance
04/06/77	174,712	333.99	rebuild carbs, cam and timing chain
03/09/77	174,679	29.99	battery
11/05/76	174,250	25.32	voltage regulator

## Mercedes 190SL Maintenance Records

1956 190SL

chassis # 551445

10/03/10



**Date            Mileage            Cost            Repair**

10/06/76	174,104	985.92	rebuild engine (top)
01/06/76	174,088	9.50	scope engine
10/10/75	172,497	13.09	points, plugs rotor
07/16/75	171,145	-	replace starter motor
05/16/75	169,700	14.06	switch and boot
04/01/75	169,700	119.20	starter motor
04/24/74	165,543	0.93	throttle return spring
01/22/74	163,609	14.12	oil change and lube
12/28/73	163,088	7.00	basket and belt
12/21/73	163,201	79.00	repair cylinder head, weld
12/17/73	163,201	167.16	adjust valves and rework cylinder head, new valves
11/28/73	162,620	6.50	points plugs and valves
11/10/73	162,353	4.40	plugs
08/10/73	160,512	1.09	shift boot
08/09/73	160,512	22.00	repair seat frames
06/08/73	159,442	16.50	adjust valves and timing
06/06/73	159,377	25.60	muffler
06/05/73	159,367	169.90	refurb vinyl interior (new dash and door top rails)
03/18/73	157,012	105.80	4 tires and wheel balance
02/26/73	155,000	14.43	water hoses, belt, and temp gauge
08/09/72	154,595	11.27	points and plugs
08/07/72	154,530	10.30	oil and lube
10/20/71	150,000	2.63	wiper blades
06/15/71	147,014	8.50	adjust timing and valve tappet clearance
05/25/71	146,454	11.00	oil and lube
05/14/71	146,339	5.00	balance and rotate tires
04/05/71	145,634	5.00	thermostat
03/18/71	145,300	22.88	front brake lines
02/23/71	144,935	126.69	rebuild clutch and t/o bearing
10/29/70	142,835	56.35	rebuild generator
10/19/70	142,500	194.00	repaint
10/19/70	142,500	15.25	hub caps
09/12/70	140,500	40.39	muffler and hangers
06/11/70	139,907	9.45	oil change and filter
06/11/70	139,907	2.00	transmission fluid change
03/15/70	137,273	95.29	4 tires, wheel balance
02/24/70	137,152	230.39	grind valves
02/24/70	137,152	50.00	clean carbs, plugs
12/15/69	136,632	129.08	repair front end
10/09/69	136,000	4.56	fuel hose parts
10/05/69	135,000	-	clean plugs, adjust carb
05/24/69	133,000	200.00	HDDUP
01/15/69	132,137	8.56	battery

# Mercedes 190SL Maintenance Records

1956 190SL  
 chassis # 551445  
 10/03/10



**Date            Mileage            Cost            Repair**

Date	Mileage	Cost	Repair
11/25/68	131,388	85.11	boil radiator, flush engine, water hoses
10/31/68	131,300	9.95	replace left motor mount
10/05/68	99,516	44.37	two tires, wheel balance
09/02/68	127,791	1.80	wiper blades
08/18/68	127,685	6.10	balance front wheels
08/05/68	127,474	64.00	4 tires and wheel balancing
08/03/68	127,391	18.00	lube and oil, plugs, adjust valves
04/27/68	125,550	15.00	repack front bearings, rotate tires
03/26/68	125,092	10.52	lube and oil change
10/16/67	123,700	77.50	new top
05/17/67	122,287	40.54	rear motor mount
05/02/67	122,134	4.91	lube and oil change
05/30/66	119,619	4.60	lube and oil change
05/01/66	119,000	22.87	battery
01/28/66	118,583	70.23	valve grinding, head gasket, manifold gasket
09/27/65	117,462	14.30	lube and oil change
05/15/65	116,380	46.44	rebuild carb, tune up
05/12/65	116,326	15.08	timing, set carb
05/10/65	116,190	32.63	tune up, points and plugs
01/15/65	114,789	4.44	thermostat
01/14/65	114,789	8.00	lube
11/15/64	113,708	7.78	motor mount
11/06/64	113,708	100.54	valve grinding, head gasket, manifold gasket
08/11/64	112,572	13.14	fuel pump repair
07/18/64	111,749	9.66	lube and oil change
06/20/64	110,000	33.84	two tires, wheel balance
06/06/64	109,960	5.00	carb linkage
06/06/64	109,960	4.90	oil change and lube
05/16/64	109,041	18.50	front end alignment
05/07/64	108,584	58.96	tune up, points and plugs
10/31/63	100,518	61.57	tune up, points and plugs